ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0132, W0157, W0155, W0161, W0300	NA, 4th Crs Lakshmi Sagar Lyt	Doddamma Temple
Segment No.	**Total Length (m)**	
7/C-W0132/S115718	381.55	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	115.58	77.600533	13.071407	77.600294	13.070389	Ayappa temple road	Dead End
2	125.48	77.600836	13.071328	77.600565	13.070225	Ayappa temple road	Dead End
3	140.49	77.601139	13.071280	77.600836	13.070046	Ayappa temple road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains of 15th to 18th Cross Roads of Jakkur Layout in ward no 07, Byatarayanapura, Kodigehalli Sub Division	5000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Providing RCC Drains.2.Providing RCC Covering Slabs	007-18-000008
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/82/17-18	02/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
23/06/2018	22/06/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	

826123

ield Inspection Details

Number of Trees	Any Other Information	Name
5		Pushpalatha.N.D
Date of Inspection	**Remarks**	
05/07/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0132, W0157, W0155, W0161,

ation	Approver Name	Date	Target Date	Remark
	R.L.Parameshwaraiah	11/07/2018	10/08/2018	As proposed
E	Vasu K M	07/07/2018	10/08/2018	Completed
EE	Mohandas H.T	06/07/2018	10/08/2018	verified
AEE	Ranganath	06/07/2018	10/08/2018	verified
AE	Pushpalatha.N.D	06/07/2018	23/07/2018	Mobile Verification Done
AE	Pushpalatha.N.D	23/06/2018	23/07/2018	Forwarded



Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0132, W0157, W0155, W0161,

Assistant Executive Engineer,
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,
Bangalore.